




It is suggested to make the servo shaft turn in the middle position when assembly the clutch.